## PROFORMA FOR THE SAFETY OF SCHOOL BUILDING PART- 1

(To be filled by the Head of School/Institute)

	(10 be filled of the flead of School/ filstitute)		
1.	Name of the School: SRI GIURU HARGIOBIND CONVENT SR. SEC SCHOOL-		
2.	Location:NATHANA, 151102, POOHLI ROAD, NATHANA.		
3.	Plot Area:28KANAL , 16. MARLA		
4			
4.	Plinth Area:5.6.5.7.7,		
5.	Number of Storey's: $03$		
6.	Year of Construction of Building:2013.		
7.	If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given		
a)	Name of the Engineer with qualification:NAVRAJSINGHGRE.WAL		
b)	Address of Engineer:- BATHINDA GOLE MARKET S.CO19		
	Set of Structural drawings used in the construction, if available:		
c)	Name & address of Architect with qualification:NAVRAJSING.HGIREWAL-		
d)	Whether the building has been constructed for the purpose		
8.			
a) b)	School  Residential Purpose and converted for use as a School		(Yes/No)
9.	Materials used for roofs		(100/110)
a)	R.C.C. Slabs/R.B.C. Slabs	:	(Yes/No)
b)	R.S. Joist & Battons	:	(Yes/No)
c)	Wooden joists & Battons	:	(Yes/No)
10.	Materials used for walls		(4.10.12.0)
a)	Mud Mortar	:	(Yeş/No)
b)	Cement Mortar	:	(Yes/No)
c)	Lime Mortar	;	(Yes/No)
11.	Flooring		
a)	Conglomerate	:	(Yes/No)
b)	Terrazo	;	(Yes/No)
c)	Brick Paving.	:	(Yes/No)
12.	A detailed drawing indicating dimensions of the rosize and location of doors and windows (Attached)		h
	Date:	Signature with	Stamp of the seal

Affiliation Code No. 1630976

(For the use of the PWD B&R department).

- a) I NISHU BANSAL S.D.E. alongwith Johnsh dap Singh J.E. have visited this school on 0305205 and have inspected it from all angles of safety and found it fit for normal use as school building.
- b) In case any addition, alteration, extension or modification of this building is to be carried out, it should be carried out under the supervision of technical qualified Engineer, and after its completion, this certificates may again be obtained from the undersigned.
- c) In case the building is affected by flood or if there is settlement to walls foundations, edging or roof, immediate inspection of the undersigned be arranged to check the stability and safety of the building.

e) Inspection fee has been deposited by the school vide G.R. No. <u>CPAISB2SOR</u>, dt. <u>3/5/25</u> amounting to Rs. <u>15,000/- Clithem therest</u> only)

Countersigned

iR

Executive Engineer,

Sub Divisional Engineer,

Provl. Sub Division No. 2, P.W.D. (B&R) Br. Bathinda

03/07/2025